

T.I. no.: 2020 - 03 Updated: -	Topic: Software SCSoul v4.12.3
---	---------------------------------------

Date: 17.02.2020	Priority	Need for action
Affected machines: SCSoul	High	As soon as possible
From serial number: 1945../	X Medium	X On next visit to the machine
As of date: KW08/2020	Low	FYI only

IMPROVEMENTS

Improvements

- Coffee machine gets stuck during the milk steps
During the parameter setting of the milk steps, it can happen that the total volume of the milk steps becomes incorrectly adjusted and the machine cannot be completely configured in the process sequence. A software crash is the consequence, necessitating a restart. The milk step change that was made could not be saved.

Software release v4.12.3 eliminates this problem and replaces software release v4.12.2.