

T.I. no.: 2020 - 07 Updated: -	Topic: Schaerer Barista – Software version 2.2.4
---	---

Date: 26.02.2020	Priority	Need for action
Affected machines: Schaerer Barista	High	As soon as possible
From serial number: -	Medium	On next visit to the machine
As of date: Immediately	X Low	X FYI only

OPTIMISATION

Incorrect identification via Coffee Link Portal

After the publication of software version 2.2.3, we were informed that the "Schaerer Barista" machines with telemetry (NGx3 protocol) were still visible in the Coffee Link Portal, but have no longer sent data.

After a check it was found that the **Schaerer Barista** machines were reported as the **WMF espresso** machine type in the Coffee Link Portal due to a software error, and the data was sent to these machine types. The error has been fixed with the software version 2.2.4.

The new software was tested during an extensive internal approval test. If, however, problems do occur during the update, please save the data on a USB stick, copy it into an e-mail and send it to Schaerer AG together with a detailed description of the problem.

E-mail address: MSAG_Tech-Support-INT@schaerer.com