


TYPE NO CV7200 – CV7300	TYPE Coffe Vending Machines	T.I. NO 02 - 2015				
SERIAL NUMBERS AFFECTED From and including S/N 42411444		ISSUED BY Documentation/N&W Valbrembo				
SUBJECT NEW PELTIER CELLS		ISSUED FOR (X): <table border="1"> <tr> <td>Action</td> <td></td> </tr> <tr> <td>Information</td> <td>X</td> </tr> </table>	Action		Information	X
Action						
Information	X					

REASON

1. In the existing “Peltier cells” the rubber caps, used to cover the screws head (see pictures below), can’t avoid the condensation accumulation over the screws head.
2. Furthermore it’s necessary an improvement of the wiring fixing.


MODIFICATIONS:

1. So to prevent a damage and consequently a complete failure of the cells, a new improved rubber cap has been introduced.



TYPE NO CV7200 – CV7300	TYPE Coffe Vending Machines	T.I. NO 02 - 2015				
SERIAL NUMBERS AFFECTED From and including S/N 42411444		ISSUED BY Documentation/N&W Valbrembo				
SUBJECT NEW PELTIER CELLS		ISSUED FOR (X): <table border="1"> <tr> <td>Action</td> <td></td> </tr> <tr> <td>Information</td> <td>X</td> </tr> </table>	Action		Information	X
Action						
Information	X					

2. Below a photo of the improved wiring fixing.



3. A self adhesive foam insulating layer (5) is glued on the basic plate of the heat sink of the new cooling device.



Machines concerned by this modification from S/N [42411444](#)

EXCHANGEABILITY:

The new “Peltier cells” solution can be installed in the machines prior to the above mentioned serial number (back compatibility)