



TYPE NO 7100 ES - FB - IN	TYPE Coffe Vending Machines	T.I. NO 03 - 2015				
SERIAL NUMBERS AFFECTED From and including S/N 41711049 (7100ES)	ISSUED BY Documentation/N&W Valbrembo					
SUBJECT STAINLESS STEEL STUDS FOR CUP STOP		ISSUED FOR (X): <table border="1"> <tr> <td>Action</td> <td><input type="checkbox"/></td> </tr> <tr> <td>Information</td> <td><input checked="" type="checkbox"/></td> </tr> </table>	Action	<input type="checkbox"/>	Information	<input checked="" type="checkbox"/>
Action	<input type="checkbox"/>					
Information	<input checked="" type="checkbox"/>					

REASON

The existing CUP STOP solution does not guarantee a good fixing.

A new solution has been introduced.



Below two pictures of the old CUP STOP



MODIFICATIONS:

The new CUP STOP is made by :

- n. 3 "cup stop male thread pin (A) - Spare part code: **259068**
- n. 3 "cup stop female thread pin (B) - Spare part code: **259067**



TYPE NO 7100 ES - FB - IN	TYPE Coffe Vending Machines	T.I. NO 03 - 2015				
SERIAL NUMBERS AFFECTED	From and including S/N 41711049 (7100ES)	ISSUED BY Documentation/N&W Valbrembo				
SUBJECT STAINLESS STEEL STUDS FOR CUP STOP		ISSUED FOR (X): <table border="1"> <tr> <td>Action</td> <td></td> </tr> <tr> <td>Information</td> <td>X</td> </tr> </table>	Action		Information	X
Action						
Information	X					



TOP view

Bottom view



Note: in the two pictures there's only one of the three steel studs used

The new cup stop solution guarantees a good fixing, thanks to the three fixed points.

Machines concerned by this modification from:

- S/N **41711049** 7100 ES
- S/N **52011304** 7100 FB
- S/N **51811218** 7100 IN

EXCHANGEABILITY:

The new cup stop solution can be installed in the machines prior to the above mentioned serial number.