

Type Coffee Vending Machine	Model 9100 - 95	N° T.I. 05 - 2022	
Serial Number 20421288	Subject NEW ACTUATION BOARD	ISSUED FOR (X)	Action Information X

REASON:

Due to the lack of *microprocessors* present on the *actuation board*

MODIFICATIONS:




A **new** *actuation board* is introduced. The main difference between the old and the new actuation board is the microprocessor and the related power supply circuit.

New actuation board

Spare code: **265409**

Pre - modification actuation board

Spare code: **261899**



Type Coffee Vending Machine	Model 9100 - 95	N° T.I. 05 - 2022					
Serial Number 20421288	Subject NEW ACTUATION BOARD	ISSUED FOR (X)	<table border="1"> <tr> <td>Action</td> <td></td> </tr> <tr> <td>Information</td> <td>X</td> </tr> </table>	Action		Information	X
Action							
Information	X						

➤ *Machines concerned by modification from S/N:* **20421288**

Important note: the **new** board must be combined with *new SW versions* below.

They will also be able to identify the type of both boards (**new** and **pre – modification**)

✓ 9100 **2.14.15** (and following)

✓ 95 **1.6.15** (and following)

Exchangeability

The **new** *actuation board* (spare code: **265409**) can be mounted on machines prior to the above S/N in place of the **pre - modification** *actuation board* (spare code: **261899**), by installing the new SW.