



SERVICE MEMO

07-11-2024

Dispenser(s): W100
Title: Cup holder clip

Background:

During first tests and installations we have seen that the cup holder fixation is sometimes breaking. Especially when you drop the cup holder.

Evoca has changed the material of this part already in production.

This material is updated in machines after serial number 44021279. Official T1 will follow.

Action:

It is advised to fixate the cup holder with screws, for first production machines <44021279 during installation. When the spare part is available it can be changed.

