


| | | | | | | | |
|---------------------------------------|---|-----------------------------|--|--------|--|-------------|----------|
| Type Coffee Vending Machine | Model 9XXX | N° T.I. 04 - 2022 | | | | | |
| Serial Number 20421345 | Subject Z4000 upper piston filter plate improvement | ISSUED FOR (X) | <table border="1"> <tr> <td>Action</td> <td></td> </tr> <tr> <td>Information</td> <td>X</td> </tr> </table> | Action | | Information | X |
| Action | | | | | | | |
| Information | X | | | | | | |

REASON:


To avoid flow meter error

MODIFICATIONS:


Ten extra studs (orange dots in the picture 3) on the Z4000 brewer upper piston base plate (filter support, part #5 in picture 1) have been implemented.




Picture 1



Picture 2



Picture 3



Picture 4 - detail

Filter support with studs Spare
part code: **256753 / 55116498**

➤ **Machines concerned by modification from S/N 20421345.**

EXCHANGEABILITY

The spare part code does not change, the new filter support is already available as spare part