







T.I. no.: 2017 - 06 Updated: -	Topic: Booster spare parts
--	-----------------------------------

Date: 28.04.2017	Priority	Need for action
Affected machines: TWIN 500	High	As soon as possible
From serial number: 1709.../	Medium	On next visit to the machine
As of date: -	X Low	X FYI only

BOOSTER SPARE PARTS

The booster (074530) will be installed in the TWIN 500 (from serial number 1709.../). This booster uses plug connections and is therefore not compatible with the old pipes.

- For machines starting with serial number 1709.../, order the new spare parts.
- If a booster needs to be replaced, the new spare parts must also be ordered.

Old booster (061823), screw connections		New booster (074530), plug connections	
063779 Pipe right		074673 Pipe right	
063780 Pipe left		074674 Pipe left	
061490 Pipe bottom		074675 Pipe bottom +8 mm length	

(EN) This page is intentionally left blank.

(DE) Diese Seite wurde absichtlich frei gelassen.

(FR) Cette page est laissée vide intentionnellement.

(ES) Esta página se dejado en blanco intencionalmente.