

<b>T.I. no.:</b> 2018 - 05 <b>Updated:</b> -	<b>Topic:</b> New drip tray
---	-----------------------------


<b>Date:</b> 27.03.2018
<b>Affected machines:</b> SC Soul
<b>From serial number:</b> 1810.../
<b>As of date:</b> -

<b>Priority</b>	
	High
X	Medium
	Low

<b>Need for action</b>	
	As soon as possible
	On next visit to the machine
X	FYI only

## NEW DRIP TRAY

The drip tray (079878) has been redone to facilitate the assembly of the drain hose and prevent incorrect assembly. In addition, the hose can now be secured with the hose clamp (066794).



**IMPORTANT**

**i** A drip tray with faulty material has been installed for machines up to and with S.N. 1752Xxx.../. Affected customers which have not yet received a new drip tray can order a new drip tray free of charge by the end of July through their normal sales contact.

(EN) This page is intentionally left blank.

(DE) Diese Seite wurde absichtlich frei gelassen.

(FR) Cette page est laissée vide intentionnellement.

(ES) Esta página se dejado en blanco intencionalmente.