

T.I. no.: 2018 - 97 Updated: -	Topic: JDE B0 Software 3.43.0 and 3.43.3
-----------------------------------	--

Date: 15.02.2018	Priority	Need for action
Affected machines: JDE B0	High	As soon as possible
From serial number: 1809../	X Medium	X On next visit to the machine
As of date: 26.02.2018	Low	FYI only

NEW FUNCTIONS AND IMPROVEMENTS IN 3.43.0

The following is an overview of the new functions and improvements:

New functions:



- New brand "Moccona" integrated (Loupe images from Friele used).
- Norwegian integrated.
- Barista button integrated.

Improvements:

- Display freeze at time of boiler timeout during cleaning fixed.

Barista button

The [Barista button visible] parameter can be enabled in "Service menu" -> "General".
The coffee strength can be adjusted using this field. 15% more or less coffee is ground.



IMPROVEMENTS 3.43.3

The following is an overview of the new functions and improvements:

Improvements:

- Beverage supply with "Free vend" works correctly. Beverage does not remain inactive.
- Beverage supply with "Value token" works correctly. Beverage is only dispensed when the correct amount/value is inserted.