

T.I. no.: 2019 - 08 Updated: -	Topic: Critical fault during cleaning
-----------------------------------	---------------------------------------

Date: 21.05.2019
Affected machines: SC Soul
From serial number: 1901.../
As of date: -

Priority	
X	High
	Medium
	Low

Need for action	
X	As soon as possible
	On next visit to the machine
	FYI only

ERROR IMAGE AND SHORT-TERM MEASURE

WARNING OF SCALDING RISK
 Due to the interplay of the software and hardware, water can spray over a large area when cleaning machines from serial number 1901.../. This water is hot and can cause scalding injuries.

A solution to the problem will be found and be available within a month. The following immediate measure must be taken until the error has been rectified.

Immediate measure

Cover the drip tray with a rag or a towel as shown in the picture. This prevents the water from spraying over a large area.



(EN) This page is intentionally left blank.

(DE) Diese Seite wurde absichtlich frei gelassen.

(FR) Cette page est laissée vide intentionnellement.

(ES) Esta página se dejado en blanco intencionalmente.