

T.I. no.: 2020 - 02 Updated: -	Topic: Additional powder container outlet restrictor
-----------------------------------	--

Date: 14.02.2020	Priority	Need for action
Affected machines: SCS powder cont. 2 kg cpl.	High	As soon as possible
From serial number: -	Medium	On next visit to the machine
As of date: KW06/2020	X Low	X FYI only


ADDITIONAL POWDER CONTAINER OUTLET RESTRICTOR

DESCRIPTION OF THE PROBLEM


The powder can become clogged with the previously installed powder container outlet restrictor (079940).

REMEDY

The Choc plate (33.2293.700) is installed ex-works and the powder container outlet restrictor (079940) is also included. In case of problems, the service technician can change them on site.



EX-WORKS: CHOC PLATE (33.2293.700)



ADDITIONALLY: POWDER CONTAINER OUTLET RESTRICTOR (079940)