












T.I. no.: 2020 - 11 Updated: -	Topic: Grinder replacement
---	-----------------------------------

Date: 30.03.2020	Priority	Need for action
Affected machines: Various	High	As soon as possible
From serial number: Effective immediately	Medium	On next visit to the machine
As of date: Effective immediately	X Low	X FYI only

THE GRINDER RANGE IS BEING SCALED DOWN

The following grinders will be replaced by grinder (064023).

This includes the grinder as well as all parts 1 to 11. Depending on the machine, the respective parts 1 to 11 must be exchanged.

Original article number	Replacement article number	1	2	3
062400	064023	 070835 Spring	 069071 SCA finger protection	 069577 E6MU finger protection
063120				
063295				
063296				
063897				
063898				
065318				
068569				
068570				
070058				
070059				
070060				
070061				
070491				
071281				
071469				
069195				
069196				
069144				
069145				
		4	5	6
		 070811 SCC finger protection	 070465 Grinder disc	 070432 Worm shaft
		7	8	
		 062425 Shaft bearing	 070629 Finger protection cover	
		9	10	11
		 062664 M4x16 (1 piece)	 062083 M4x20 (1 piece)	 062442 M5x12 (3 pieces) 3x