



Type <b>Coffee Vending Machine</b>	Model <b>95</b>	N° T.I. <b>01 - 2020</b>
Serial Number <b>93811697</b>	Subject <b>Modification of CUP SENSOR WIRING</b>	ISSUED Action FOR (X) Information <b>X</b>

➤ In addition to the modification above, to help the production line assembling, the **pre-modification door wiring** has been divided into the **modified door wiring** + **new keypad wiring**

○ **Pre-modification door wiring** spare code: **261897**      It is no longer available

✓ **Modified door wiring**      spare code: **262895**

✓ **New keypad wiring**      spare code: **262897**

➤ **Machines concerned by modification from S/N 93811697**

**EXCHANGEABILITY:**

For machines previous to S/N above, it's possible to have the **new** solution by ordering the spare parts:

1. **262895**    **modified door wiring**
2. **262897**    **new keypad wiring**
3. **261898**    **modified cup sensor wiring**      (spare code not changed)