

Type Coffee Vending Machine	Model C2100 – C3100	T.I. NO 10 - 2016
Serial Number 63911589	Subject NEW BOILER COVER ASSEMBLY	ISSUED FOR (X) Action Information X

REASON

It's required to create the **support** fixing points to improve the fixing of the *electronic board*



MODIFICATIONS:

Two holes have been added in the *Boiler solenoid valve support*. They are used to fix the **electronic control board** showed below.

New Boiler cover Assembly



Boiler solenoid valve Support



Support with the *electronic control board*

TECHNICAL INFORMATION JDE



Type Coffee Vending Machine	Model C2100 – C3100	T.I. NO 10 - 2016
Serial Number 63911589	Subject NEW BOILER COVER ASSEMBLY	ISSUED FOR (X)
		Action Information
		X

Machines concerned by this modification from S/N: 63911589

The *Boiler cover Assembly* spare code in not changed: 30964600

EXCHANGEABILITY:

For the machines prior to the above mentioned serial number it's possible to implement the new *Boiler cover Assembly*.