

|                                       |                                      |  |
|---------------------------------------|--------------------------------------|--|
| Type<br><b>Coffee Vending Machine</b> | Model<br><b>9100</b>                 | N° T.I.<br><b>03 - 2021</b>                      |
| Serial Number<br><b>13521476</b>      | Subject<br><b>TOUCHSCREEN UPDATE</b> | ISSUED FOR (X)<br>Action<br>Information <b>X</b> |

**REASON:**

Due to a production process optimization at the supplier

**MODIFICATIONS:**

A new Touchscreen version has been released with a **new System key 3.0.10-1**

**New Touchscreen**  
Spare part code: **264505**

**Pre-modification Touchscreen**  
Spare part code: **260321**



**Important note:**

- **WARNING!** DO NOT downgrade a new TS to a System Key lower than 3.0.10-1.
- It's possible to upgrade a pre-modification touchscreen to the System Key 3.0.10-1 (or higher), even if it's not mandatory.

➤ Machines concerned by modification from S/N **13521476**.