

<b>T.I. no.: 2018 - 16</b> Updated: -	<b>Topic: SCA P Software 6.10</b>
--	-----------------------------------

<b>Date: 23.07.2018</b>	<b>Priority</b>	<b>Need for action</b>
<b>Affected machines: SCA P</b>	High	As soon as possible
<b>From serial number: 1828../</b>	X Medium	X On next visit to the machine
<b>As of date: -</b>	Low	FYI only

## NEW FUNCTIONS AND IMPROVEMENTS

The following is an overview of the new functions and fixed errors:

### New functions:

- Telemetry integrated via MDB Comms gateway.
- Most current version of M2M integrated.
- Simultaneous dispensing possible for all beverages thanks to swan neck. (only CH)
- The product ID can be freely defined for networked accounting.
- Time is correctly set when M2M is connected.
- Thai characters can be displayed on the TouchIT.
- The brewing time display is activated in the Quick menu. The brewing time is displayed after beverage dispensing.
- A new [Vend on Credit] parameter in the MDB configuration also enables beverage supply when no balance exists. This is needed if billing is done via a network.

### Improvements

#### Accounting system

- More than two token channels are supported.
- Malfunction meaning that no beverages are dispensed despite credit being available has been fixed.
- MDB level 3 is no longer set to level 2 after a rinsing.
- Time delay of the beverage button release when using a card reader and DIVA reduced.
- Unspecified credit is detected correctly, but not shown.
- Beverages which have the price 0.00 are correctly detected (DIVA).
- If the complete remaining amount cannot be dispensed because there is not enough money, a message is output. The beverages which can be dispensed with the remaining amount are then available.
- Card credit of 0.00 is displayed correctly.
- Activated MDB interface without existing payment system no longer causes the machine to block when starting.
- Price lists can be copied in the MDB menu.

#### Telemetry

- The telemetry module is displayed when the machine goes into standby mode.
- The brewing time is correctly detected by the telemetry when the beverage is cancelled.

## Miscellaneous

- After activating Centre Milk, the machine no longer restarts automatically.
- Service menu button is displayed correctly.
- New logo integrated.
- CUP card has only read rights.
- "Erase card" works correctly.
- Switching on when the timer is used works correctly.
- Unnecessary output variants removed, e.g. "Portion control" for coffee beverages.
- Screensaver is hidden during beverage supply via external buttons and rinsing.
- Article numbers of the beverages are displayed in the statistics and in the price list.
- Various text adaptations.
- "Flavour Point in operation" hidden for CHEF card.
- After beverage supply, the standard beverage page is always displayed.  
If the [] parameter is set to "0", the last remaining beverage page remains selected.
- If the Flavour Point in the Service menu is deactivated, all associated parameters are deactivated.
- Switching off with CHEF card works correctly.
- The "Barista" preselection is reset after 5 seconds.
- Pump is automatically activated when dispensing into pots.
- Mandatory cleaning is only triggered when a beverage has been dispensed since the last cleaning.
- Access to USB stick optimised.
- Planned mandatory cleaning is done correctly even if the machine is switched off.
- When cleaning the Flavour Point, the pumps now run for 3 x 60 seconds.