


Service Memo

2019-006

Machine: Schaerer Coffee Art BF
Titel: Schaerer Coffee Art BF INSERT BEVERAGE OUTLET WELDED: 55121245 (075139)

Dear All,

With this service memo I want to inform you that the Insert beverage outlet BF 074408 is changed into INSERT BEVERAGE OUTLET WELDED 075139 with Sap number : 55121245:



Introduced since week 22.

Problem was that there was a possibility that the outflow for the double cup was not equal.
They changed the way of production to solve this.